

石頭金[®]

MetalMiracle[®]

LYCORES[®]

Sichuan MetalMiracle Industry Corp.

Slewing Rings apply to Excavators including but not limited to the following items:

| NO. | TYPE | NO. | TYPE | NO. | TYPE | NO. | TYPE | NO. | TYPE | NO. | TYPE |
|------------|------------------|------------|---------|----------------|-------------|-------------|---------|------------|----------|-----|--------------|
| 小松 KOMATSU | | 51 | PC450-6 | 100 | SK200-5 | 149 | HD700-5 | 198 | DH215-7 | 247 | JCB220 |
| 1 | PC30-2 | 52 | PC450-7 | 101 | SK200-6 | 150 | HD700-7 | 199 | DH225-7 | 248 | CASE55 |
| 2 | PC30 (Z=92) | 日立 HITACHI | | 102 | SK210-6E | 151 | HD770-1 | 200 | DH280 | 249 | CASE210B |
| 3 | PC50-7 | 53 | EX40-1 | 103 | SK200-8 | 152 | HD770-2 | 201 | DH290 | 250 | 九五60 |
| 4 | PC55 | 54 | EX60-1 | 104 | SK07-1 | 153 | HD800-7 | 202 | DH300-5 | 251 | 三一65 |
| 5 | PW60-5 | 55 | EX60-2 | 105 | SK07-2 | 154 | HD770SE | 203 | DH300-7 | 252 | 三一75 |
| 6 | PC60-5 | 56 | EX60-3 | 106 | SK907B | 155 | HD800-5 | 204 | DH10L | 253 | 三一135 |
| 7 | PC60-6(Z=76) | 57 | EX60-5 | 107 | SK07-N2 (1) | 156 | HD820-3 | 205 | DH370-7 | 254 | 三一200 |
| 8 | PC60-6(Z=80) | 58 | EX75 | 108 | SK07-N2 (2) | 157 | HD820-1 | 206 | DH420 | 255 | 力士德70 |
| 9 | PC60-7(Z=76) | 59 | EX90 | 109 | SK235 | 158 | HD900-7 | 207 | DH320 | 256 | 力士德80 |
| 10 | PC60-7(Z=80) | 60 | EX100-1 | 110 | SK260-8 | 住友 SUMITOMO | | 208 | DH330-3 | 257 | 力士德200 |
| 11 | PC90-6 | 61 | EX120-1 | 111 | SK230-6 | 159 | SH60-1 | 现代 HYUNDAI | | 258 | 力士德360 |
| 12 | PC100-5 | 62 | EX120-2 | 112 | SK330-3 | 160 | SH120A1 | 209 | R55-7 | 259 | 振宇80 |
| 13 | PC120-5 | 63 | EX120-3 | 113 | SK350 | 161 | SH120-1 | 210 | R60-5 | 260 | 振宇150 |
| 14 | PC120-6(4D95) | 64 | EX120-5 | 114 | SK450-6E | 162 | SH120A2 | 211 | R60-7 | 261 | 振宇210 |
| 15 | PC120-6(4D102) | 65 | EX200-1 | 卡特 CATERPILLAR | | 163 | SH120-2 | 212 | R80-7 | 262 | 柳工907 |
| 16 | PC150-5 | 66 | EX200-2 | 115 | E305.5 | 164 | SH120A3 | 213 | R110-7 | 263 | 柳工908 |
| 17 | PC150-7 | 67 | EX200-3 | 116 | E306 | 165 | SH120-3 | 214 | R130-5 | 264 | 柳工200 (Z=86) |
| 18 | PC20HT | 68 | EX200-5 | 117 | E70B | 166 | SH120Z3 | 215 | R130-7 | 265 | 柳工230(Z=91) |
| 19 | PC200-1 | 69 | EX210-5 | 118 | E307B | 167 | SH120C3 | 216 | R170-5 | 266 | 柳工936 |
| 20 | PC200-2 | 70 | EX220-5 | 119 | E307C | 168 | SH140 | 217 | R200 | 267 | 山河45 |
| 21 | PC200-3 | 71 | EX300-1 | 120 | E308 | 169 | SH145 | 218 | R200-5 | 268 | 山河50 (Z=83) |
| 22 | PC200-5 | 72 | EX300-2 | 121 | E110 | 170 | SH200A1 | 219 | R210 | 269 | 山河60 |
| 23 | PC200-8 | 73 | EX400-1 | 122 | E120 | 171 | SH200A2 | 220 | R210-5 | 270 | 山河70 |
| 24 | PC210-7 | 74 | EX300-3 | 123 | E200B | 172 | SH200A3 | 221 | R210-3 | 271 | 山河80 |
| 25 | PC220-3 | 75 | EX400-3 | 124 | E215 | 173 | SH200C2 | 222 | R200-7 | 272 | 山河210 |
| 26 | PC220-5 | 76 | EX300-5 | 125 | E215B | 174 | SH200C3 | 223 | R210-7 | 273 | 山河240 |
| 27 | PC200-6(S6D95) | 77 | ZX60 | 126 | E312B | 175 | SH200Z3 | 224 | R215-7 | 274 | 玉柴35 |
| 28 | PC200-6(S6D102) | 78 | ZAX70 | 127 | E320B | 176 | SH220 | 225 | R220-5 | 275 | 玉柴60-8 |
| 29 | PC200-6(S6D102)A | 79 | ZX120 | 128 | E320C | 177 | SH240-5 | 226 | R225-7 | 276 | 玉柴85 |
| 30 | PC200-6(6D102) | 80 | ZX200 | 129 | E320D | 178 | SH240-3 | 227 | R260LC-7 | 277 | 玉柴135 |
| 31 | PC220-6(S6D95) | 81 | ZX210 | 130 | E320L | 179 | SH225 | 228 | R290 | 278 | 厦工820 |
| 32 | PC220-6(S6D102) | 82 | ZX200-3 | 131 | E225 | 180 | SH260 | 229 | R300 | 279 | 厦工823 |
| 33 | PC200-7(Z=110) | 83 | ZX210 | 132 | E280 | 181 | SH265 | 230 | R305-7 | 280 | 勤牛60 |
| 34 | PC200-7(Z=92) | 84 | ZX225U | 133 | E325 | 182 | SH280 | 231 | R335-7 | 281 | 龙工60 |
| 35 | PC220-7(Z=92) | 85 | ZX230 | 134 | E311 | 183 | SH300-2 | 232 | R305LC-7 | 282 | 龙工210 |
| 36 | PC227 | 86 | ZX240 | 135 | E325B | 184 | SH340 | 233 | R450-7 | 283 | 汉拿200 |
| 37 | PC228/32孔 | 87 | ZX270 | 136 | E325C | 185 | SH350 | 其他 | | 284 | 石川岛60 |
| 38 | PC228/40孔 | 88 | ZX330 | 137 | E330C | 186 | SH430 | 234 | 三星PS132 | 285 | 竹内175 |
| 39 | PC300-2 | 89 | ZX350-5 | 加藤 KATO | | 187 | SH40T | 235 | 三星PS210 | 286 | 雷沃60 |
| 40 | PC300-3 | 90 | ZX450H | 138 | HD250-7 | 大宇 DOOSAN | | 236 | 三星MX08-2 | 287 | 雷沃85 |

| | | | | | | | | | | | |
|----|---------|------------|---------|-----|---------|-----|-----------|-----|-------------|-----|-----------|
| 41 | PC300-5 | 91 | UH063 | 139 | HD307 | 188 | DH55-3 | 237 | 三星292 | 288 | 雷沃260 |
| 42 | PC300-6 | 神钢 KOBELCO | | 140 | HD308 | 189 | DH55-5 | 238 | LIEBHERR934 | 289 | 山东卡特45 |
| 43 | PC350-6 | 92 | SK03 | 141 | HD450-5 | 190 | DH80GO | 239 | LIEBHERR924 | 290 | 山东卡特50 |
| 44 | PC360-7 | 93 | SK60-5 | 142 | HD450-7 | 191 | DH80-7 | 240 | LIEBHERR914 | 291 | 山东卡特60 |
| 45 | PC400-1 | 94 | SK100 | 143 | HD512 | 192 | DH150 | 241 | 沃尔沃EC210B | 292 | 山东卡特80 |
| 46 | PC400-3 | 95 | SK09 | 144 | HD513 | 193 | DH200-3 | 242 | 沃尔沃EC210 | 293 | 詹阳210 |
| 47 | PC400-5 | 96 | SK120-5 | 145 | HD516 | 194 | DH220-2 | 243 | 沃尔沃EC290 | 294 | 沃尔沃EC700B |
| 48 | PC450-5 | 97 | SK200-1 | 146 | HD550 | 195 | DH220-3 | 244 | 沃尔沃EC360 | | |
| 49 | PC400-6 | 98 | SK200-2 | 147 | HD100 | 196 | DH220-5 | 245 | 三菱230 | | |
| 50 | PC400-7 | 99 | SK200-3 | 148 | HD700-2 | 197 | DH220-7LC | 246 | 阿特拉斯3306 | | |

There are Part Number information as below:

| PN | Remarks |
|--------------|---|
| 2276082 | 37 holes on outer ring |
| 20Y-25-28110 | |
| JSB0022 | 38 holes on outer ring,43 holes on inner ring |
| JRB0017 | 31 holes on outer ring,36 holes on inner ring |
| 21P-25-K1100 | |
| 21K-25-33100 | |
| KRB10160 | |
| 227-6081 | |
| 229-1077 | |
| 227-6081 | |
| 81N6-00023 | |
| JRB0017 | 31 holes on outer ring,36 holes on inner ring |
| YN40F00026F1 | |
| 20Y-25-21200 | |
| 206-25-00200 | |
| 207-25-61100 | |
| VOE14647523 | |
| | |
| 201-25-51100 | |
| 201-25-61100 | |
| 201-25-61100 | |
| 201-25-72102 | |
| 201-25-72102 | |
| 201-25-72102 | |
| 21W-25-42100 | |
| 203-25-51200 | |
| 203-25-51200 | |
| 203-25-51200 | |
| 203-25-61101 | |
| 203-25-61101 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 203-25-62100 | |
| 21K-25-33100 | |
| 21K-25-33100 | |
| 21K-25-33100 | |
| 21K-25-00101 | |
| 21K-25-00101 | |
| 21K-25-00101 | |
| 205-25-00015 | |

| |
|--------------|
| 9129521 |
| 9166468 |
| 9196498 |
| 9196498 |
| 9184497 |
| 9169646 |
| 9169646 |
| 9260971 |
| 9169646 |
| 9196732 |
| 9154037 |
| 9245728 |
| 9154037 |
| 9166468 |
| 9166468 |
| 9129521 |
| |
| 2425U261F1 |
| 2425U252F1 |
| 24100N7529F1 |
| LP40FU0001F1 |
| 24100N7529F1 |
| YY40F00009F1 |
| YY40F00009F1 |
| 24100N7529F1 |
| 24100N7440F1 |
| 24100N7440F1 |
| 24100N7440F1 |
| 24100N7440F1 |
| 24100N7440F1 |
| YN40F00020F1 |
| YN40F00020F1 |
| YN40F00026F1 |
| YN40F00014F1 |
| LQ40F00014F1 |
| 24100N7441F1 |
| LC40F00009F1 |
| LC40F00018F1 |
| LS40FU0001F1 |
| LS40FU0001F1 |
| LS40F00003F1 |
| LS40F00003F1 |
| |
| 229-1077 |
| 229-1077 |
| 229-1077 |
| 229-1077 |
| 229-1077 |
| 229-1077 |
| 7Y1563 |
| 227-6081 |
| 227-6081 |
| 7Y1563 |
| 8K4127 |
| 227-6087 |
| 227-6089 |
| |
| KNB0434 |
| KNB0434 |
| KNB0434 |

| |
|--------------|
| KNB0434 |
| KBB0413 |
| KBB0413 |
| KSB10070 |
| KSB10070 |
| |
| 2109-9067A |
| K1008340 |
| K1008340 |
| 109-00052B |
| 109-00052B |
| 109-00052B-A |
| 109-00162-A |
| 109-00030B-A |
| 2109-1053B |
| 2109-1053B |
| 2109-1053B |
| 109-00161-A |
| 2109-9035A |
| 2109-9035A |
| 2109-9035A |
| 140109-00039 |
| 140109-00039 |
| 140109-00039 |
| 2109-9067A |
| |
| 1155-00061 |
| 14505766 |
| 14520573 |
| 14563350 |
| 14563350 |

The catalog did not include all machinery information.
For your special requests, please do contact us so that meet your demands successfully.

Sichuan MetalMiracle Industry Corp.
Tel. 86 28 85718737 Email: simon@lycores.com
www.lycores.com

Tianfu Avenue South Section NO.2039, HuaYang, Chengdu Tianfu New Area, China.
Industry area, ChongZhou, Chengdu, China.
Industry area, ChongQing, China.
Mechanical Industry area, Maanshan, China.